


FIG.1



Inventor: Schaff et al.
Docket No.: STL10416/40046.180USU1
Title: IN-SITU DETECTION OF TRANSDUCER MAGNETIC INSTABILITY IN A DISC DRIVE
Attorney No.: 365-357.1644
Sheet 3 of 6





FIG. 3

Inventor: Schaff et al.

Docket No.: STL10416/40046.180USU1

Title: IN-SITU DETECTION OF TRANSDUCER MAGNETIC INSTABILITY IN A DISC DRIVE
Attorney In Control of the Control



Inventor: Schaff et al.
Docket No.: STL10416/40046.180USUI
Title: IN-SITU DETECTION OF TRANSDUCER MAGNETIC INSTABILITY IN A DISC
DRIVE
Attorney Na
Phone No.: 30.—31.1644
Sheet 5 of 6




FIG. 5

Inventor: Schaff et al.
Docket No.: STL10416/40046.180USU1
Title: IN-SITU DETECTION OF TRANSDUCER MAGNETIC INSTABILITY IN A DISC DRIVE
Attorn Cere: John R. Wahl
Phone N. 103.357.1644
Sheet 6 of 6




FIG. 6